

Daily GLOWBUGS

Digest: V1 #131

via AB4EL Web Digests @ SunSITE

Purpose: building and operating vacuum tube-based QRP rigs

[AB4EL Ham Radio Homepage @ SunSITE](#)

%%%% GlowBugs %%%%% GlowBugs %%%%% GlowBugs %%%%% GlowBugs %%%%%

Subject: glowbugs V1 #131

glowbugs

Wednesday, October 8 1997

Volume 01 : Number 131

Date: Tue, 7 Oct 1997 11:38:05 -0400 (EDT)

From: kim herron <kherron@voyager.net>

Subject: Heath V7-A VTVM and RF probe for sale

For sale. One working Heath VTVM, and PK-3 RF probe. with the manuals.
\$25.00 shipped to you door CONUS.]

Kim Herron

kherron@voyager.net or kherron@vixa.voyager.net

1-616-677-3706

Date: Tue, 07 Oct 1997 10:38:03 -0400

From: Todd Nichols <nichols@rtp.ericsson.se>

Subject: Re: Audio transformers - substitutes?

Roberta J. Barmore wrote:

>

> AES sells 3:1 iron for not too much past the point of pain; they also
> sell just the wound bobbin for half the price, which could be combined
> with a junkbox core or one from a dead audio for a budget approach.

>

> 73,

> --Bobbi

I think I'll spring for the \$11 to get a "good" transformer from
AES in the next few days, then build up my regen and try these
different transformers in there. Should provide some interesting
results, with the AES "good" transformer as a "golden standard"
for comparative purposes.

Todd

- - -

Todd Nichols KB0HQU Ericsson Inc. (919) 472-7590
nichols@rtp.ericsson.se Research Triangle Park, NC
.sig is offline

Date: Wed, 8 Oct 1997 11:42:33 -0400 (EDT)
From: kim herron <kherron@voyager.net>
Subject: More Stuff FS

Hi Gang,

Two more items that need more attention than I can give them:

1. I have a nice working Hammarlund HQ-170 receiver. I restored this piece to electrical working condition and put the proper knobs on it. It needed a meter and so it got that. What it needs is a little repair work to the trim ring around the front panel. The paint on the plastic lettering on the front panel is red, not silver. I've been told that the factory did this on a few units. Why I don't know. With a little effort you could repaint silver, provided your hand is steadier than mine. I have the paint for the trim ring, and a manual (170/170a Service manual-150+pages). This is a good working receiver that still needs some finishing work done to it. Please find a good home for it. \$150 plus some help with the shipping.

2 I have a TEK scope camera. Model C-5A. This is a working camera and it uses Polaroid film. It doesn't fit my 'scope and I'm not sure what scope it fits (Stan Griffiths, your phone is ringing). It has a flash intensity control and a small door to view the scope through. This is what I know about this unit. \$25.00 shipped to anywhere in the lower 48 states.

That's it for the moment. I could use some info on a Heath SS9000 if anyone knows anything about it. I have a chance to buy one (what for!?) and would like to know what I should be paying. Thanks gang.

Kim Herron
kherron@voyager.net or kherron@vixa.voyager.net
1-616-677-3706

End of glowbugs V1 #131

%%%% GlowBugs %%%%% GlowBugs %%%%% GlowBugs %%%%% GlowBugs %%%%%

[AB4EL Ham Radio Homepage @ SunSITE](#)

Created by Steve Modena, AB4EL

Comments and suggestions to **modena@SunSITE.unc.edu**
